9. General Diagnostic Table

A: INSPECTION

1. IMPROPER VEHICLE POSTURE OR IMPROPER WHEEL ARCH HEIGHT

Possible causes	Countermeasures
(1) Permanent distortion or breakage of coil spring	Replace.
(2) Unsmooth operation of damper strut and/or shock absorber	Replace.
(3) Installation of wrong strut and/or shock absorber	Replace with proper parts.
(4) Installation of wrong coil spring	Replace with proper parts.

2. POOR RIDE COMFORT

1) Large rebound shock

- 2) Rocking of the vehicle continues too long after running over bump and/or hump.
- 3) Large shock in bumping

Possible causes	Countermeasures
(1) Breakage of coil spring	Replace.
(2) Overinflation pressure of tire	Adjust.
(3) Improper wheel arch height	Adjust or replace the coil springs with new ones.
(4) Fault in operation of damper strut and/or shock absorber	Replace.
(5) Damage or deformation of strut mount and/or shock absorber mount	Replace.
(6) Unsuitable installation (maximum and/or minimum length) of damper strut and/or shock absorber.	Replace with proper parts.
(7) Deformation or damage of bushing	Replace.
(8) Deformation or damage of helper in strut assembly and/or shock absorber	Replace.
(9) Oil leakage of damper strut and/or shock absorber	Replace.

3. NOISE

Possible causes	Countermeasures
(1) Wear or damage of damper strut	Replace.
(2) Wear or damage of shock absorber component parts	Replace.
(3) Loosening of suspension link installing bolt	Retighten to the specified torque.
(4) Deformation or loss of bushing	Replace.
(5) Unsuitability of maximum and/or minimum length of damper strut and/or shock absorber	Replace with proper parts.
(6) Breakage of coil spring	Replace.
(7) Wear or damage of ball joint	Replace.
(8) Deformation of stabilizer clamp	Replace.